

FAGOR  Fagor Automation	Software update WINDRAW55 (V2.02)	Date: Jan. 14th, 2009
	From: CNC Marketing Department For: Internal use only	Page 1 of 1

INDEX

<u>1 Software Updates.....</u>	<u>1</u>
<u>1.1 #23270 Windows problems after installing Windraw55.....</u>	<u>1</u>

1 SOFTWARE UPDATES

1.1 #23270 Windows problems after installing Windraw55

On pc's with an old operating system (Windows 95, 98 or NT), sometimes, after having installed the Windraw55 application, on startup, the pc would show the error "Windows 98 must be re-installed" because some dll files were updated with more recent ones.

From this version on, an error message will appear in applications with Windows 95, 98 or NT when detecting incompatibilities.